


Event Overview

Event: Pit 4 Receiving Conveyor Tail Section Tail Shaft Speed - under speed

Company: Your Company Name
 Location: Your Facility Name
 Equipment: Pit 4 Receiving Conveyor
 Status: Event is closed.
 Date: 2011-03-08 Time: 10:23:09
 Section Name: Tail Section Node ID: 33
 Input Name: Speed Tail Shaft Input Number: 5
 Input Value 134 RPM
 Warning Value 134 RPM
 Shutdown Value 119 RPM
 Abs Shutdown Value: N/A



Notes: _____

_____ Closed By: Your Plant Manager
 _____ Closed Date: 3/9/2011 9:50:41 AM

Cause Summery:

Your Employee - 2011-03-09 08:45:38

Conveyor began slipping under load.

Inspected the conveyor and determined that the conveyor need adjustment and that it was not over loaded.

Resolution Summery:

Your Employee - 2011-03-09 08:50:23

we increased the tension on the belt and that successful resolved the problem

Your Plant Manager - 2011-03-09 09:50:41

Event closed by user.